

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

7/87




FIG. 7

FIG. 5 is a perspective view of a frame assembly 520. The assembly includes a top rail 800 with two sliding components 814. Below the rail is a horizontal member 802, which is connected to a vertical member 804. A horizontal member 806 is positioned below 802, and a horizontal member 808 is positioned below 806. The entire assembly is supported by a vertical frame 812.

FIG. 8C

9/87




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14A




FIG. 14B




FIG. 15




FIG. 17A




FIG. 17C




FIG. 17B




FIG. 17D




FIG. 18




FIG. 19





FIG. 20






FIG. 22

23/87





FIG. 23








FIG. 24B






FIG. 26




FIG. 27




FIG. 28




FIG. 29

30/87




FIG. 30




FIG. 31

31/87




FIG. 32




FIG. 33




FIG. 34A




FIG. 34B




FIG. 35A




FIG. 35B

35/87




FIG. 35C




FIG. 36

37/87




FIG. 37A




FIG. 37B




FIG. 38A




FIG. 38B




FIG. 39A




FIG. 39B




FIG. 40




FIG. 41





FIG. 42



I-I

FIG. 42A





FIG. 42B



II-II
FIG. 42C




FIG. 42D




FIG. 42E




FIG. 43




FIG. 44




FIG. 45

52/87




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52A




FIG. 52B




FIG. 52C




FIG. 53A




FIG. 53B




FIG. 53C




FIG. 54




FIG. 55A




FIG. 55B




FIG. 56




FIG. 57




FIG. 58A




FIG. 58B




FIG. 59




FIG. 60




FIG. 61




FIG. 62








FIG. 63








FIG. 68




FIG. 69




FIG. 70




FIG. 71




FIG. 72







FIG. 73







FIG. 77






FIG. 79




FIG. 80




FIG. 81




FIG. 82




FIG. 83




FIG. 84

86/87




FIG. 85




FIG. 86




FIG. 87




FIG. 88




FIG. 89